

FIG. 3  
PRIOR ART




FIG. 4  
PRIOR ART




FIG. 5

46

44

48

4/16




FIG. 6

48 Bytes maximum misalignment

FIG. 13





FIG. 14  
PRIOR ART

5/16




FIG. 7




FIG. 8

7/16




FIG. 9

1060470 "EST3260






FIG. 10

9/16






FIG. 15

11/16




FIG. 16

11/16/98 9:57 AM 32/50




FIG. 17

12/16




FIG. 18




FIG. 19

13/16




FIG. 20

14/16

09-64538-040900




FIG. 21

15/16




FIG. 22

16/16




FIG. 23